Print Control Wizard

How to Evaluate the Gradient

esko

1. Gradient

To judge the print quality one important aspect is the quality of the gradient. It needs to be smooth, without tonal jumps and homogeneous. Here are examples what is okay and what is not okay.

Fade	
Ok	Not ok
_FADE85 _FADE75 _FADE65	_FADE85 _FADE75 _FADE65