


Print Control Wizard

How to Create the Pixel Boost Step Test


11 - 2019

1. Evaluate

1. Send the Steptestfile from the Device-Manager or Merger to the Exposer of the CDI, make sure it is the top-most job in the queue.



2. At the CDI in the Exposer go to "Options", "Preferences"




3. Type in these parameters:


Start Value: 150

Step Value: 25

Tracks: 12



4. Go to “Options”, “Step Test”



5. Load the plate and run the job

