




# Print Control Wizard


How to Create the Pixel Boost Step Test

# 1. Evaluate

1. Send the Steptestfile from the Device- Manager or Merger to the Exposer of the CDI, make sure it is the top-most job in the queue.
2. At the CDI in the Exposer go to "Options", "Preferences"
3. Type in these parameters:  
 Start Value: 150  
 Step Value: 25  
 Tracks: 12



4. Go to "Options", "Step Test"



5. Load the plate and run the job

